



Inspection Certificate

Project: --

Client: **CIRCOR Energy**
405 Centura Court, Spartanburg, SC -29303
USA.

Office: **Chicago**

Client's Order Number: **Request for Services signed and dated 22 June 2017**
PO#108570

Date: **05 July 2017**

Order Status: **Complete**

Inspection Dates

First: **29 June 2017**

Final: **05 July 2017**

This certificate is issued to **CIRCOR Energy, that the undersigned Surveyor to Lloyd's Register Quality Assurance, Inc., did at their request attended their works on and between the aforementioned dates for the purpose of verifying, witnessing tests on the items detailed below to the following scope of inspection:**

Ferrule Size	Tube Set-up Size/Material/Mill Heat#	Quantity Tested
10FRD50mm-XP-NK	10mm x 2.0mm/6Mo/HC#4G	6 Nos.
12FRD50mm-XP-NK	12mm x 2.0mm/6Mo/HC#525	6 Nos.
18FRD50mm-XP-NK	18mm x 2.0mm/6Mo/HC#489	6 Nos.
20FRD50mm-XP-NK	20mm x 2.5mm/6Mo/HC#0979	6 Nos.
25FRD50mm-XP-NK	25mm x 2.0mm/6Mo/HC#1088	6 Nos.
10FR316mm-XP	10mm x 2.0mm/316/HC#361	6 Nos.
12FR316mm-XP	12mm x 2.0mm/316/HC#469	6 Nos.
18FR316mm-XP	18mm x 2.0mm/316/HC#361	6 Nos.
20FR316mm-XP	20mm x 2.0mm/316/HC#0964	6 Nos.
16FR316mm-XP	1" x .120"/316/HC#1167	6 Nos.
12FRD50mm-XP-NK	12mm x 2.0mm/316-6Mo/HC#525	4 Nos.
18FRD50mm-XP-NK	18mm x 2.0mm/316-6Mo/HC#489	4 Nos.

Scope of Inspection:

1. Identified Ferrule and Tube material with part numbers and manufacturer's drawing.
2. Reviewed internal records, calibration records and production testing procedure.
3. Witnessed burst test on the Ferrules per manufacturers test set-up and procedure.
4. Carried out visual examination of Ferrule for finish, profile per drawing requirements.
5. Manufacturer's Ferrule's Testing Data Log endorsed.

Note:

1. The above inspection was undertaken at the request of the client and does in no way relieve the client/manufacturer of its responsibilities of complying with all statutory requirements including statutory inspection requirements of any importing country.

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Conclusion:

Based on the above scope of inspection, the material described is considered by the undersigned to comply with the manufacturers' specification and drawing requirements.

-End-



Raju Cunkari
Surveyor to Lloyd's Register Quality Assurance, Inc.

a member of the Lloyd's Register group.